

40 \_ 35 \_ 30 \_ F = 1,00525 + F= 1.01 **2**0 F = 1.0215 F = 1.0510 F = 1.15 0 i 50 100 150 200 DPn

FIG 1b

**REPLACEMENT SHEET (RULE 26)** 




FIG 2